


Heatsink U2 must be connected to power supply ground.

	Date	Name	Description	Page: 1 of 1
	Jan. 18, 2017	AJP	CNC Router Single 1 Axis Stepper Motor Driver TB6560 (3A)	
	Dec. 12, 2017	Corrected R16		
	Bit-Bucket 's-Hertogenbosch ©		Schematic no.	
			Version:	1.01