

Portable four-trace oscilloscope

PM3264

Instruction Manual/Gerätehandbuch/Notice d'emploi et entretien

9499 443 02502
840209/06/..

S&I

Scientific & Industrial Equipment Division



**Scientific &
Industrial Equipment**

PHILIPS




Fig. 8.17. Power supply, circuit diagram






Fig. 8.19. Z-amplifier, focus unit and auxiliary unit, circuit diagram




Fig. 8.20. Z-amplifier, printed circuit board lay-out




Fig. 8.24. Wiring lay-out of PM 3264